


Technical requirements

- 1.Fill grease into all active parts.
- 2.After assembly, the gap between main frame and the movable frame should be not more than 1mm.
- 3.The handbook shall be painted according to ZPMC painting.
- 4.The fasteners shall be painted.
- 5.The cable box is a spare part.

技术要求

- 1.各活动关节处应定时加注润滑油,螺母涂松乐奉胶。
- 2.移动架上下滑动间隙不得大于1mm。
- 3.按公司规定的本项目油漆工艺进行油漆处理。
- 4.紧固件安装完成后,涂油漆保护,颜色同所在部位构件。
- 5.储线柜为备用件,平时不安装。

[illegible]