

PPA Central Passenger Port Upgrades

Before & After Presentation – May
2025

Underground Karaiskaki Car Parking Station

Before




After




Complete resurfacing, new markings, and EV spots added.

Reconstruction of Concrete Stairs

Before



After



Stairs rebuilt with reinforced concrete and safety railings.


New Zebra Crossings for Pedestrian Safety




High-visibility pedestrian crossings added at key locations.

Pedestrian Bridge Restoration

Before




After




Escalators restored and structural repainting completed.

Dock Marking – Black/Yellow Safety Pattern

Before



After




Bright diagonal yellow-black patterns improve visibility and dockside safety.

Road Surface Renewal – Tzelepi Coast

Before



After



Damaged asphalt replaced with durable concrete to resist wear and salinity.

Installation of shading systems in ferry area for the facilitation of passengers



Four (4) out of six (6) new shading systems have already been installed at the ferry area.